



中国认可
国际互认
检测
TESTING
CNAS L0446



TEST REPORT

CheckCode:975537
Report No.:C202603058609-1E

Company Name: Playbox AB
Address: Spångatan 4, 343 34 Älmhult, Sweden

The following sample information is provided by the client and responsible for its authenticity

Sample Name: Play sand 5 kg natural colour
Specifications: 2472015
LOT NO.: 12591
Supplier: 833

Date of Receipt: Mar.13, 2026 **Test Period:** Mar.13, 2026 – Mar.17, 2026

Test Request: As specified by client, to determine Asbestos content in the submitted sample(s).

Test Result: Please refer to following page(s).



Edited by Cheng Wanfen Reviewed by Chen Jiaying Approved by Cheng Wanfen



扫一扫 验真伪



The result(s) shown in this report refer(s) only to the sample(s) tested. This report is considered invalid without approved signature, special seal for inspection and testing and the seal on the perforation. This report cannot be reproduced except in full, without prior written approval of the company. Any disagreements of the test report should be fed back to us within 15 workdays upon receiving the report. Scan the QR code on the first page of the test report, or log on to the official website <http://www.grgtmall.com>, enter the report number and check code to check the authenticity of the report. If you have any questions, please contact the email grgttest@grgttest.com. GRGT assumes no responsibility for information leakage caused by improper management of the QR code and the check code by customers.

GRG METROLOGY & TEST GROUP CO., LTD.

Add: No.8, Chuangyun Road, Panyu District, Guangzhou, Guangdong, China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgttest.com>

TEST REPORT

CheckCode:975537
Report No.:C202603058609-1E

Sample Description:

Sample No.	Description
1	Brown play sand

Instrument:

Instrument	Manufacturer	Model	Testing
X-ray powder diffractometer (XRD)	Rigaku	Ultima-IV	Qualitative, Quantitative
Polarizing microscope (PLM)	leica	DM 2700P	Qualitative

Test Result(s):

Test Method: With reference to ISO 22262-1:2012 and NIOSH 9000:2015, analysis was performed by Polarizing microscope (PLM) and X-ray powder diffractometer (XRD).

Test Item	CAS No.	Sample	MDL
		1	
Chrysotile	12001-29-5	Negative	0.1%(m/m)
Amosite	12172-73-5	Negative	0.1%(m/m)
Crocidolite	12001-28-4	Negative	0.1%(m/m)
Anthophyllite	77536-67-5	Negative	0.1%(m/m)
Tremolite	77536-68-6	Negative	0.1%(m/m)
Actinolite	77536-66-4	Negative	0.1%(m/m)


- Remark:
- 1) Negative < 0.1%(m/m) (Not detected asbestos), Positive ≥ 0.1%(m/m) (Detected asbestos)
 - 2) MDL = Method Detection Limit
 - 3) 1 mg/kg = 1 ppm = 0.0001%(m/m)

GRG METROLOGY & TEST GROUP CO., LTD.

Add: No.8, Chuangyun Road, Panyu District, Guangzhou, Guangdong, China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgtest.com>

TEST REPORT

CheckCode:975537
Report No.:C202603058609-1E



-----End of Report-----



中国认可
国际互认
检测
TESTING
CNAS L0446



TEST REPORT

CheckCode:473886
Report No.:C202603058609-3E

Company Name: Playbox AB
Address: Spångatan 4, 343 34 Älmhult, Sweden

The following sample information is provided by the client and responsible for its authenticity

Sample Name: Play sand 1 kg pink
Specifications: 2472019
LOT NO.: 12768
Supplier: 833

Date of Receipt: Mar.13, 2026 **Test Period:** Mar.13, 2026 – Mar.17, 2026

Test Request: As specified by client, to determine Asbestos content in the submitted sample(s).

Test Result: Please refer to following page(s).

Edited by Cheng Wanfen Reviewed by Chen Jiaying Approved by Chen Jiaying



扫一扫 验真伪



The result(s) shown in this report refer(s) only to the sample(s) tested. This report is considered invalid without approved signature, special seal for inspection and testing and the seal on the perforation. This report cannot be reproduced except in full, without prior written approval of the company. Any disagreements of the test report should be fed back to us within 15 workdays upon receiving the report. Scan the QR code on the first page of the test report, or log on to the official website <http://www.grgtest.com>, enter the report number and check code to check the authenticity of the report. If you have any questions, please contact the email grgtest@grgtest.com. GRGT assumes no responsibility for information leakage caused by improper management of the QR code and the check code by customers.

GRG METROLOGY & TEST GROUP CO., LTD.

Add: No.8, Chuangyun Road, Panyu District, Guangzhou, Guangdong, China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgtest.com>

TEST REPORT

CheckCode:473886
Report No.:C202603058609-3E

Sample Description:

Sample No.	Description
1	Rose play sand





Instrument:

Instrument	Manufacturer	Model	Testing
X-ray powder diffractometer (XRD)	Rigaku	Ultima-IV	Qualitative, Quantitative
Polarizingmicroscope(PLM)	leica	DM 2700P	Qualitative

Test Result(s):

Test Method: With reference to ISO 22262-1:2012 and NIOSH 9000:2015, analysis was performed by Polarizingmicroscope (PLM) and X-ray powder diffractometer (XRD).

Test Item	CAS No.	Sample	MDL
		1	
Chrysotile	12001-29-5	Negative	0.1%(m/m)
Amosite	12172-73-5	Negative	0.1%(m/m)
Crocidolite	12001-28-4	Negative	0.1%(m/m)
Anthophyllite	77536-67-5	Negative	0.1%(m/m)
Tremolite	77536-68-6	Negative	0.1%(m/m)
Actinolite	77536-66-4	Negative	0.1%(m/m)


- Remark:
- 1) Negative<0.1%(m/m) (Not detected asbestos),Positive≥0.1%(m/m) (Detected asbestos)
 - 2) MDL= Method Detection Limit
 - 3) 1 mg/kg=1 ppm=0.0001%(m/m)

GRG METROLOGY & TEST GROUP CO., LTD.

Add: No.8,Chuangyun Road,Panyu District,Guangzhou,Guangdong,China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgtest.com>

TEST REPORT

CheckCode:473886
Report No.:C202603058609-3E



-----End of Report-----



中国认可
国际互认
检测
TESTING
CNAS L0446



TEST REPORT

CheckCode:223061
Report No.:C202603058609-4E

Company Name: Playbox AB
Address: Spångatan 4, 343 34 Älmhult, Sweden

The following sample information is provided by the client and responsible for its authenticity

Sample Name: blue sand color 400g
Specifications: HF-2472388A
LOT NO.: 12906
Supplier: 833

Date of Receipt: Mar.13, 2026 **Test Period:** Mar.13, 2026 – Mar.17, 2026

Test Request: As specified by client, to determine Asbestos content in the submitted sample(s).

Test Result: Please refer to following page(s).



Edited by Cheng Wanfen Reviewed by Chen Jiaying Approved by Cheng Wanfen



扫一扫 验真伪



The result(s) shown in this report refer(s) only to the sample(s) tested. This report is considered invalid without approved signature, special seal for inspection and testing and the seal on the perforation. This report cannot be reproduced except in full, without prior written approval of the company. Any disagreements of the test report should be fed back to us within 15 workdays upon receiving the report. Scan the QR code on the first page of the test report, or log on to the official website <http://www.grgtmall.com>, enter the report number and check code to check the authenticity of the report. If you have any questions, please contact the email grgttest@grgttest.com. GRGT assumes no responsibility for information leakage caused by improper management of the QR code and the check code by customers.

GRG METROLOGY & TEST GROUP CO., LTD.

Add: No.8, Chuangyun Road, Panyu District, Guangzhou, Guangdong, China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgttest.com>

TEST REPORT

CheckCode:223061
Report No.:C202603058609-4E

Sample Description:

Sample No.	Description
1	Blue play sand

Instrument:

Instrument	Manufacturer	Model	Testing
X-ray powder diffractometer (XRD)	Rigaku	Ultima-IV	Qualitative, Quantitative
Polarizingmicroscope(PLM)	leica	DM 2700P	Qualitative

Test Result(s):

Test Method: With reference to ISO 22262-1:2012 and NIOSH 9000:2015, analysis was performed by Polarizingmicroscope (PLM) and X-ray powder diffractometer (XRD).

Test Item	CAS No.	Sample	MDL
		1	
Chrysotile	12001-29-5	Negative	0.1%(m/m)
Amosite	12172-73-5	Negative	0.1%(m/m)
Crocidolite	12001-28-4	Negative	0.1%(m/m)
Anthophyllite	77536-67-5	Negative	0.1%(m/m)
Tremolite	77536-68-6	Negative	0.1%(m/m)
Actinolite	77536-66-4	Negative	0.1%(m/m)




- Remark:
- 1) Negative<0.1%(m/m) (Not detected asbestos),Positive≥0.1%(m/m) (Detected asbestos)
 - 2) MDL= Method Detection Limit
 - 3) 1 mg/kg=1 ppm=0.0001%(m/m)

GRG METROLOGY & TEST GROUP CO., LTD.

Add: No.8, Chuangyun Road, Panyu District, Guangzhou, Guangdong, China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgtest.com>

TEST REPORT

CheckCode:223061
Report No.:C202603058609-4E



-----End of Report-----





中国认可
国际互认
检测
TESTING
CNAS L0446



TEST REPORT

CheckCode:724711
Report No.:C202603058609-2E

Company Name: Playbox AB
Address: Spångatan 4, 343 34 Älmhult, Sweden

The following sample information is provided by the client and responsible for its authenticity

Sample Name: green sand color 400g
Specifications: HF-2472388B
LOT NO.: 12906
Supplier: 833

Date of Receipt: Mar.13, 2026 **Test Period:** Mar.13, 2026 – Mar.17, 2026

Test Request: As specified by client, to determine Asbestos content in the submitted sample(s).

Test Result: Please refer to following page(s).



Edited by Cheng Wanfen Reviewed by Chen Jiaying Approved by Chen Jiaying



扫一扫 验真伪



The result(s) shown in this report refer(s) only to the sample(s) tested. This report is considered invalid without approved signature, special seal for inspection and testing and the seal on the perforation. This report cannot be reproduced except in full, without prior written approval of the company. Any disagreements of the test report should be fed back to us within 15 workdays upon receiving the report. Scan the QR code on the first page of the test report, or log on to the official website <http://www.grgtest.com>, enter the report number and check code to check the authenticity of the report. If you have any questions, please contact the email grgtest@grgtest.com. GRGT assumes no responsibility for information leakage caused by improper management of the QR code and the check code by customers.

GRG METROLOGY & TEST GROUP CO., LTD.
Add: No.8, Chuangyun Road, Panyu District, Guangzhou, Guangdong, China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgtest.com>

TEST REPORT

CheckCode:724711
Report No.:C202603058609-2E

Sample Description:

Sample No.	Description
1	Green play sand

Instrument:

Instrument	Manufacturer	Model	Testing
X-ray powder diffractometer (XRD)	Rigaku	Ultima-IV	Qualitative, Quantitative
Polarizing microscope (PLM)	leica	DM 2700P	Qualitative

Test Result(s):

Test Method: With reference to ISO 22262-1:2012 and NIOSH 9000:2015, analysis was performed by Polarizing microscope (PLM) and X-ray powder diffractometer (XRD).

Test Item	CAS No.	Sample	MDL
		1	
Chrysotile	12001-29-5	Negative	0.1%(m/m)
Amosite	12172-73-5	Negative	0.1%(m/m)
Crocidolite	12001-28-4	Negative	0.1%(m/m)
Anthophyllite	77536-67-5	Negative	0.1%(m/m)
Tremolite	77536-68-6	Negative	0.1%(m/m)
Actinolite	77536-66-4	Negative	0.1%(m/m)


- Remark:
- 1) Negative < 0.1%(m/m) (Not detected asbestos), Positive ≥ 0.1%(m/m) (Detected asbestos)
 - 2) MDL = Method Detection Limit
 - 3) 1 mg/kg = 1 ppm = 0.0001%(m/m)

GRG METROLOGY & TEST GROUP CO., LTD.

Add: No.8, Chuangyun Road, Panyu District, Guangzhou, Guangdong, China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgtest.com>

TEST REPORT

CheckCode:724711
Report No.:C202603058609-2E



-----End of Report-----